


Reparatursatz Repair kit

Reparatursatz ZF20 M1P4 28 U/min Lüfter und Haube
Repair kit ZF20 M1P4 28 rpm fan and hood



Pos.	Bezeichnung Description	Menge Quantity
605	Lüfterhaube M1 normal S=1 L=60,5 - RAL2004 Fan cover M1 normal S=1 L=60,5 - RAL2004	1 Stück 1 piece
601	Lüfter M71 2-8P PA6 Fan M71 2-8P PA6	1 Stück 1 piece
607	Gewindefurchschraube DIN 7500-D - M 5 x 8 A2F Screw DIN 7500-D - M 5 x 8 A2F	4 Stück 4 pieces

Knauf PFT GmbH & Co. KG
 Einersheimer Str. 53
 97346 Iphofen, Germany

Technical Hotline +49 9323 31-1818
 info@pft.net
www.pft.net

Part no. 00595464
Made in Germany

