


Reparaturatz Repairkit

Reparaturatz SK25 Stufe 2 Repair kit SK25 stage 2



Pos.	Bezeichnung Description	Menge Quantity
400	Lager Bearing	1 Stück 1 piece
700	Ritzelwelle Pinion shaft	1 Stück 1 piece
701	Antriebsrad Drive gear	1 Stück 1 piece
711	Lager Bearing	1 Stück 1 piece

Knauf PFT GmbH & Co. KG
Einersheimer Str. 53
97346 Iphofen, Germany

Technical Hotline +49 9323 31-1818
info@pft-iphofen.de
www.pft.net

Part no. 00 61 88 10
Made in Germany

