


Reparaturatz Repairkit

Reparaturatz SK25 Flansch Repair kit SK25 flange



Pos.	Bezeichnung Description	Menge Quantity
400	Flansch Flange	1 Stück 1 piece

Knauf PFT GmbH & Co. KG
Einersheimer Str. 53
97346 Iphofen, Germany

Technical Hotline +49 9323 31-1818
info@pft-iphofen.de
www.pft.net

Part no. 00 61 88 04
Made in Germany

